

FIG. 1




FIG. 2

, i i i




FIG. 3

1 4 4 4




FIG. 4




FIG. 5






FIG. 6




FIG. 7

	OPERATION	R/C SELECT STATUS	kow Row	COLUMN	V SOURCE	> OXIDE	RESULT
₩ 801	PROGRAM	SR/SC	2.5	7.0	0	7.0	PROGRAM
802 -		SR/UC	2.5	0	0	0	NO CHANGE
803		UR/SC	0	0.7	0	۸ 4	NO CHANGE
804		UR/UC	0	0	0	0	NO CHANGE
805	READ	SR/SC	2.5	1.5	0		CURRENT
\$00		SR/UC	2.5	0	0		NO CURRENT
807 —		UR/SC	0	1.5	0		NO CURRENT
₹ 808		UR/UC	0	0	0		NO CURRENT

FIG. 8

	OPERATION	R/C SELECT STATUS	V ROW	COLUMN	V SOURCE	V OXIDE	RESULT
♦ 01	PROGRAM	SR/SC	7.0	7.0	0	6.6	PROGRAM
\$05 →		SR/UC	7.0	0	0	0	NO CHANGE
\$003 →		UR/SC	0	0.7	0	< 4.0	NO CHANGE
♣ 604		UR/UC	0	0	0	0	NO CHANGE
4 — 906	READ	SR/SC	2.5	1.5	0		CURRENT SENSED
↑ 906		SR/UC	2.5	0	0		NO CURRENT
← ∠06		UR/SC	0	1.5	0		NO CURRENT
♣ 806		UR/UC	0	0	0		NO CURRENT

FIG. 9

	OPERATION	R/C SELECT STATUS	V ROW	COLUMN	V SOURCE	V OXIDE	RESULT
1001	PROGRAM	SR/SC	2.5	2.5	- 4.5	6.6	PROGRAM
1002-		SR/UC	2.5	0	- 4.5	4.0	NO CHANGE
1003-▶		UR/SC	0	2.5	-4.5	< 4.0	NO CHANGE
1004→		UR/UC	0	0	- 4.5	< 4.0	NO CHANGE
1005→	READ	SR/SC	2.5	1.5	0		CURRENT SENSED
1006→		SR/UC	2.5	0	0		NO CURRENT
1007		UR/SC	0	1.5	0		NO CURRENT
1008→		UR/UC	0	0	0		NO CURRENT

FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16